DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: 69.28

WELDING INSPECTION REPORT

Resident Engineer: Pursell, Gary **Report No:** WIR-007864 Address: 333 Burma Road **Date Inspected:** 27-Jun-2009

City: Oakland, CA 94607

OSM Arrival Time: 645 **Project Name:** SAS Superstructure **OSM Departure Time:** 1845 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island Location: Shanghai ,China

CWI Name: CWI Present: Yes Li Yan Hua No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A N/A N/A **Electrode to specification:** Yes No Weld Procedures Followed: Yes No N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

Bridge No: 34-0006 **Component:** OBG Assembly

Summary of Items Observed:

On this date CALTRANS OSM Quality Assurance (QA) Inspector was present during the times noted above for observations relative to the work being performed.

This QA Inspector carried out Segment green tag tracking for NDT performed on the OBG segments in the various repair yards. It was found that the percentage of NDT verification performed by CALTRANS Quality Assurance inspectors was sufficient. The NDT verification was tracked on the following OBG segments; 5CE, 5CW, 6AE, 6BE and 7AE. The records for NDT carried out by CALTRANS Quality Assurance inspectors on all of the OBG Segment green tagging is currently up to date.

Unless otherwise noted, all work observed on this date appeared to generally comply with applicable contract documents.

Summary of Conversations:

No Relevant conversations

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Eric Tsang, (15000422372), who represents the Office of Structural Materials for your project.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

Inspected By: Patterson, Rodney Quality Assurance Inspector

Reviewed By: Carreon, Albert QA Reviewer